

Images speak louder than words. As displayed in the following pictures, NO-BURN<sup>®</sup> Wood Gard was applied to the raw wood of a condominium complex under construction in the Canadian province of Alberta. Work on the structure proceeded up to the drywall installation. Beginning on a Friday evening, an electrical problem developed, starting an electrically-induced fire. Due to the site being unattended, the problem continued over the weekend. A full-scale fire was averted numerous times over that weekend due to the protection provided by NO-BURN<sup>®</sup>. As you can see, there is very minimal damage due to the NO-BURN<sup>®</sup> Wood Gard protecting the raw wood.

A total structural loss was avoided. NO-BURN<sup>®</sup> saves lives, time, and money.

